FIG.1A




FIG.1B




FIG.2A







FIG.2B












FIG.4


STEP A1



STEP B1




STEP C1




WO 2005/022654

FIG.5

STÉP D1



STEP E1









FIG.6




## STEP H1




# STEP I1






## STEP K1



## STEPL1



STEP M1








FIG.8














FIG.10B



10/58

FIG.11A








FIG.12



12/58

FIG.13








FIG.15

## STEP A2



## STEP B2



# STEP C2






FIG.16

STEP D2



STEP E2



STEP F2






FIG.17



STEP H2








FIG.18


STEP J2



STEP K2




STEP L2




18/58

FIG.19


## STEP M2



# STEP N2



STEP 02




19/58


PCT/JP2004/011713

**FIG.20** 

## STEP P2

WO 2005/022654





#### STEP R2




FIG.21A

2102





FIG.21B


2102




21/58


**FIG.22** 

# STEP A3







## STEP C3




**FIG.23** 

STEP D3






#### STEP F3




23/58

FIG.24


STEP G3



## STEP H3




STEP 13




24/58

FIG.25

STEP J3



STEP K3









FIG.26



## STEP N3




STEP 03




26/58

FIG.27

# STEP P3




# STEP Q3



PCT/JP2004/011713

FIG.28A 2202 2226 D01 D02 D03 2226 2226 2226 D06 D04 D05 2236A 2234A 2234B 2226 D07 **D08** D09 2204 2230 - 2232

FIG.28B








FIG.29

#### STEP A4



## STEP B4



## STEP C4







FIG.30



## STEP E4




STEP F4




30/58

**FIG.31** 


# STEP G4



## STEP H4




# STEP 14




**FIG.32** 


## STEP J4




#### STEP K4




#### STEP L4



**FIG.33** 








FIG.35A





FIG.35B



35/58

FIG.36A

2334






FIG.36B

2334





36/58

FIG.37




**FIG.38** 






39/58



WO 2005/022654



-

FIG.42A




FIG.42B




FIG.43A




FIG.43B




FIG.44




FIG.45A





FIG.45B



45/58

FIG.46A




FIG.46B




FIG.47A




FIG.47B








FIG.47C



**FIG.48** 













FIG.49












FIG.50


STEP 15




## STEP J5




## STEP K5











## STEP N5











FIG.52

## 3200










FIG.54A





FIG.54B



54/58

FIG.55A




FIG.55B





FIG.56

WO 2005/022654



56/58

FIG.57




FIG.58A

WO 2005/022654




FIG.58B

